





918.3105	1 x		1/4" TORSIONpower □□, 25mm PH1	□□□□□□□□
918.3110	2 x		1/4" TORSIONpower □□, 25mm PH2	□□□□□□□□
918.3115	1 x		1/4" TORSIONpower □□, 25mm PH3	□□□□□□□□
918.3205	1 x		1/4" TORSIONpower □□, 25mm PZ1	□□□□□□□□
918.3210	2 x		1/4" TORSIONpower □□, 25mm PZ2	□□□□□□□□
918.3215	1 x		1/4" TORSIONpower □□, 25mm PZ3	□□□□□□□□
918.3305	1 x		1/4" TORSIONpower □□, 25mm, □□□ 3mm	□□□□□□□□
918.3310	1 x		1/4" TORSIONpower □□, 25mm, □□□ 4mm	□□□□□□□□
918.3315	1 x		1/4" TORSIONpower □□, 25mm, □□□ 5mm	□□□□□□□□
918.3320	1 x		1/4" TORSIONpower □□, 25mm, □□□ 6mm	□□□□□□□□
918.3405	1 x		1/4" TORSIONpower □□□□□, 25mm, 3mm	□□□□□□□□
918.3410	1 x		1/4" TORSIONpower □□□□□, 25mm, 4mm	□□□□□□□□
918.3415	1 x		1/4" TORSIONpower □□□□□, 25mm, 5mm	□□□□□□□□
918.3420	1 x		1/4" TORSIONpower □□□□□, 25mm, 6mm	□□□□□□□□
918.3505	1 x		1/4" TORSIONpower □□ Torx, 25mm, T10	□□□□□□□□
918.3510	1 x		1/4" TORSIONpower □□ Torx, 25mm, T15	□□□□□□□□
918.3515	1 x		1/4" TORSIONpower □□ Torx, 25mm, T20	□□□□□□□□
918.3520	1 x		1/4" TORSIONpower □□ Torx, 25mm, T25	□□□□□□□□
918.3525	1 x		1/4" TORSIONpower □□ Torx, 25mm, T27	□□□□□□□□
918.3530	1 x		1/4" TORSIONpower □□ Torx, 25mm, T30	□□□□□□□□
918.3535	1 x		1/4" TORSIONpower □□ Torx, 25mm, T40	□□□□□□□□
918.3605	1 x		1/4" TORSIONpower □□ Torx, 25mm, TB10, □□	□□□□□□□□
918.3610	1 x		1/4" TORSIONpower □□ Torx, 25mm, TB15, □□	□□□□□□□□
918.3615	1 x		1/4" TORSIONpower □□ Torx, 25mm, TB20, □□	□□□□□□□□
918.3620	1 x		1/4" TORSIONpower □□ Torx, 25mm, TB25, □□	□□□□□□□□
918.3625	1 x		1/4" TORSIONpower □□ Torx, 25mm, TB27, □□	□□□□□□□□
918.3630	1 x		1/4" TORSIONpower □□ Torx, 25mm, TB30, □□	□□□□□□□□
918.3635	1 x		1/4" TORSIONpower □□ Torx, 25mm, TB40, □□	□□□□□□□□