

## TPMS service set for tire pressure monitoring systems 08

Article No.: 149.1008

EAN: 4042146628751

Promotional price: €5.00 \*



### Description

- for manufacturer VDO
- the entire valve service set of the sensor must be replaced with every tyre change or tyre service
- suitable for steel or aluminium rims

### Technical data:

Tightening torque of the nut 8 Nm

### Application range / for:

Mazda: 3, 5, 6, CX7, MX5

Reference number: 72-20-218, TPK66072, 7000K

### Properties

Application range:	Mazda
OEM code:	TPK66072, 7000K, 72-20-218
Packaging contents:	1
Packaging height, mm:	20
Packaging length, mm:	66
Packaging width, mm:	23
Weight [g]:	9